

2022 SILER – repair exhaust muffler



After proper cleaning inlet of the muffler a visible bad connection to the housing and crack in the pipe itself.



At the bottom bad connections and signs of earlier repairs by previous owner.

2022 SILER – repair exhaust muffler



Inlet pipe repaired with additional layer of GRP.



Bottom part fully filled with epoxy till flush.