

Wiring schematic (series wound motor)




Diagram No.
P101840