



Buzzer sounded at 1300 RPM and 2000 RPM.

This problem was fixed by placing 1/16" thick washers behind the spacers holding this bracket. This moved the bracket forward and stopped the buzzing.